

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst.Engineer)
(Re:G.O.Ms.20/70/PWD Dt.23-01-1970)

- 1 Name of the Officer : **BIJIMOL P P**
- 2 Name of the School : Sree Saraswathy Vidyamandir, Karikode.
- 3 Location with name of Education District/
Sub District : Karikode, Kaduthuruthy, Kuravilangadu Sub dist.
- Classification of building as specified in column
4 of the application for fitness certificate and size. :
- Block-I**
- Ground & First Floor 47.6 x 6.50 x 3.4 m (RCC Building)
Third Floor 47.6 x 6.50 x 3.40 m (Sheet roof with celing)
- Block - II**
- Ground & First Floor 20.35 x 8.90 (RCC Building)
Third Floor 14.20 x 8.90 (Sheet roof with celing)
Third Floor 6.0 x 6.30 (RCC Roofing)
- Block - III**
- Ground & First Floor 27.50 x 9.20 x 3.45 (RCC Building)
- Nursery Block**
- 19.10 x 6.50 x 2.70 (Sheet roof with celing)
20.70 x 6.50 x 3.70 (Sheet roof with celing)
- 5 Period for which the certificate is issued. : **2026-2027**
- 6 Nature of defects, if any
- a. Foundation & Basement
- b. Superstructure
- c. Doors & windows
- d. Wood work wrought and put up Nil
- e. Roof
- f. Flooring
- f. Miscellaneous (Cracks etc.)
- 7 Any major defects noticed which will render the building Unsafe in any manner : No
- 8 Weather maintenance works have been done properly : Yes
- 9 Weather the structure is sound or not for conducting classes. Yes, Structure is sound for conducting classes under normal weather conditions.

(P.T.O.)

Failure to comply with these conditions may result in the withdrawal or cancellation of this Fitness Certificate and such other action as may be deemed necessary by the competent authority.


CERTIFICATE

Certified that the school building was inspected by me on 29/5/24 and found to be fit to conduct classes, 2026 - 27 for the reasons stated above.

Place: Peruva

Date: 30/05/2026

(Seal)



BIJIMOL P.P
Assistant Engineer

BIJIMOL.P.P
ASSISTANT ENGINEER
PEN No - 479517
LID & EW SECTION
MULAKULAM G.P.